FIRE RISK ASSESSMENT HOLY TRINITY CHURCH

Address	Holy Trinity Church
	Link Top
	Malvern
	WR14 4LR
Used as	Church for services, choir and other rehearsals, teaching and occasional concerts and meetings
Date of Assessment	October 2024
Agreed by JCC	28 January 2025
Name of Assessor	R Lawrence
Review Date	October 2025

Property Description

Traditional high vaulted church with approx. 400 sq m of floor space with rows of fixed pews. 2 separate smaller side rooms approx. 20 sq m used for meetings and storage.

Attached tower which has storage space of approx. 20 sq m in the basement section

How a Fire Could Start

Possible ignition sources include:

Gas boiler in tower basement – area adjacent to boiler kept clear and monitored to remove any combustible material.

Candles in use during services only – kept away from combustibles

Electrical fault in main wiring or in portable appliance (PAT testing of all portable appliances carried out annually under contract) Main wiring inspected every five years.

Arson – building securely locked overnight and at weekends but open for public access daily (unstaffed)

Lightning –lightning conductor fitted to tower checked annually

People Affected by Fire

Congregation attending services and those attending rehearsals, concerts and meetings, etc. Usually less than 150 in total

Cleaning and admin staff and users of the organ or piano

Escape Routes

Exit doors to south, west and east of the central area. All are (or can be easily) unlocked during services and concerts

West door level access and ramp at south door for wheelchair users

Fire Alarm

All exit doors have emergency lights tested monthly and recorded. Emergency lights also tested annually for three hour test.

Fire Extinguishers

Distributed at various important points near doors are:

5 CO2, extinguishers, 4 Foam extinguishers

All are maintained annually under contract and details recorded

Fire Action

Evacuation via any of the three exit doors Fire assembly point on lawn to the north of church and adjacent to Parish Hall

Signs located at strategic points explain what to do in case of fire.

No public access telephone boxes nearby so Fire Brigade need to be called through 999 by mobile.

Persons in charge of services or concerts are briefed on fire action to be taken.

Fire Information

Copies of this assessment have been passed to administrator and members of the committee responsible for the church

Records of all maintenance, testing and any important changes are kept in the vestry next to north exit door.

Review Date	Comments